Section 1	MANAGEMENT OF	CHANGE	(MOC)				ABU:		Plant:	Year:
МОС		Date Issued:	Passport I		EWO	No:	RLOP		LNHF 13 Plant	2010
2279	Watson, Stephanie J.	11/5/2010								
Section :	2 Reviewer: MOC Category:	PSM:		N	IOC Type:		Expiration Date:	Oth	ner Temporary Reason	
Seidlitz,	Michael R. Routine			P	ermanent					
Project/Equi	ipment Title: R-1310 Max Bed Tem	perature override (@ 750F and lo	ow prio	rity alarm @	760F	- Update EOM w	ith E	Bed Temperature Limit	
	of Change:									
60F will be	as been created to change the R-13 a high alarm and the metallurgical a	larm at 825F will n	ot be change	d and	will be a hig	h-high a	alarm.	•		
ecycle gas. not have en esulted in h process con	peratures in R-1310 should remain be. High molecular weight gases increading power to recycle the gas through recycle gas molecular weight. Anditions. The recycle rate and other pall information.	ase the recycle cor gh the LNF. During s a result, the K-13	mpressor pow g a 7R run in : 00 horsepow	ver requ Septen er requ	uirement. If nber/Octobe iirements ex	the receiver 2010 the contract of the contract	cycle gas become R-1310 bed tem I the capacity of	es to pera the o	oo heavy, the compresso atures went as high as 78 compressor for the existi	r will 80F and ng
The 750F m	nax bed temperature is below the poi was chosen so there is a buffer bet						ity of the compre	essoi	r driver. The 750F bed	
MOC will be	e required if the change will:									
Cause	e the use of different feed, chemicals	or catalysts?								
✓ Cause	e the use of different process condition	ons, process contro	ol, instrument	ation, a	and protecti	ve devi	ces or affect ups	trear	m/downstream plants?	
Cause	e the use of new or modified equipme	ent [which is other	than inkind]?							
Alter	equipment siting, building, trailer loca	tions, roads or fire	protection?							
✓ Requi	re modifying existing and/or develop	ng new procedure	s?							
Section 2						✓ Sir	multaneously Be	gin (Construction and Start-up	0
Stage	Dro Implementation	Dept./Pe	rson		Date		Completed By		Poforonco	
1	Pre-Implementation	Respon	sible	_ C	Complete		Completed By		Reference	5
	Design Review	ļ								
_	Process Engineering Review	Watson, Steph	anie J.		11/5/2010	Watso	n, Stephanie J.			
-	Instrumentation Review									
-	Control System Review	Carter, Grady E	Ξ	#	#########	Carter	, Grady E.			
-	Utilities Review									
	Environmental/Regulatory Review	Tarter, Donald	J.		11/8/2010	Tarter	Donald J.			
L	Safety/Regulatory Review									
	Building Permits Review	Linares, Elena	E.		11/8/2010	Linare	s, Elena E.			
	Mechanical Review									
	Inspection Review									
	Metallurgy Review									
	Contruction Review									
	Leak Seal Review									
	Relief System Review	Î								
_	Infrastructure Review									
	PHA/HSE Review	Watson, Steph	anie J.		12/8/2010	Watso	n, Stephanie J.			
	and the state of t									
	tion to Implement Change (Begin Co			eidlitz,	Michael R.			Date	e: 12/10/2010	
Stage	Pre-Startup	Dept./Pe Respon		0	Date Complete		Completed By		Reference	s
2	Procedures Review	Henrickson, Ala		_	1/11/2011	Henric	kson, Alan C.			
-	Communication/Training 1	Henrickson, Ala		_	1/11/2011	_	kson, Alan C.			
l +	Pre Start-up Safety Review	Watson, Steph	CONTRACT DATE	_	2/22/2011		on, Stephanie J.			
	The State-up Salety Neview	vvaison, oteph	anic o.	+	LILLIZOTT	vvatoc	ni, otephanie o.			
Authorizat	tion to Start-Up Change:		Approver: So	eidlitz,	Michael R.			Date	e: 2/22/2011	
Extensio Approve		pprover:				Ехр	iration Date:	E	Extention Reason	
Stage 3	Post-Startup	Dept./Pe Respon		(Date Complete		Completed By		Reference	s
	Communication/Training				0.10.0.10.0.1.1		I B () E			
	Process Safety Information	McCall, Patrick	D.		2/22/2011	McCa	II, Patrick D.			
Change in	Place - Reviews, App	rover:				Date		1		
	table of Tarthan Committee	dlitz, Michael R.				2/22/				

MOC Cancelled:

Approver:
Cancellation Reason:

Note 1: Emergency request for change should be routed by the Approver on the next working day

Retain Original in Division for five Years

PROCESS ENGINEERING REVIEW CHECKLIST MOC Number 22794 Filing Reference You have been assigned a Process Engineering Review. This checklist is a guide to help ensure that all information Watson, Stephanie J. Person Responsible necessary to evaluate the change is considered. Completed By Watson, Stephanie J. Project/Equipment Title: Date Completed 11/5/2010 R-1310 Max Bed Temperature override @ 750F and low priority alarm @ 760F - Update EOM with Bed Temperature Limit DOCUMENTATION SUMMARY OF REVIEW* Drafting Work Requisition, MFG-5545

Impacts

PROCESSES REVIEW	
ASTM-TBP-EFV Distillation Relationships	☐ Suppliers' Performance
BIN Best Practice	Surface Tensions
Characterization of Petroleum Fractions	☐ Thermal Properties
Composition & Flow Information	Upstream & Downstream
Conversion Factor & Constants	☐ Vapor-Liquid Equilibria
Delivery Needs	☐ Vapor Pressures
Densities	
Fundamental Properties	
Honeywell	
Honeywell Process Simulator	
Material & Energy Balance	
New Catalyst of Feeds	
✓ Operating Parameters	
Physical Properties of Streams or Catalysts	

All bed temperatures in R-1310 should remain below 750F to prevent excessive cracking in R-1310. Excessive cracking increases the molecular weight of the recycle gas. High molecular weight gases increase the recycle compressor power requirement. If the recycle gas becomes too heavy, the compressor will not have enough power to recycle the gas through the LNF. During a 7R run in September/October 2010 R-1310 bed temperatures went as high as 780F and resulted in high recycle gas molecular weight. As a result, the K-1100 horsepower requirements exceeded the capacity of the compressor for the existing process conditions. The recycle rate and other process variables began oscilatting, which caused the plant to become unstable. Refer to IMPACT ERM LI#7 for additional information.

The 750F max bed temperature is below the point (780F) that K-1300 HP requirements exceed the capacity of the compressor. The 750F bed temperature was chosen so there is a buffer between the point at which the compressor had issues.

As discussed above this temperature limit has a large buffer (~30F). R-1310 could operate above 750F and still be in a stable condition. However, there should be hightened awareness of the yields, recycle gravity, and compressor operation if this limit is changed in the future.

*When possible include copies of documents referenced in the summary.

Solubilities

MSDS's

PED Records

Relief System Drawings

CONTROL SYSTEM REVIEW CHECKLIST

You have been assigned a Control System Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

MOC Number	22794
Filing Reference	
Person Responsible Completed By Date Completed	Carter, Grady E.
	Carter, Grady E.
	11/10/2010

Project/Equipment Description:

This MOC has been created to change the R-1310 bed temperature override high setpoint limit to 750F and add a low priority alarm at 760F. The alarm at 760F will be a high alarm and the metallurgical alarm at 825F will not be changed and will be a high-high alarm.

All bed temperatures in R-1310 should remain below 750F to prevent excessive cracking in R-1310. Excessive cracking increases the molecular weight of the recycle gas. High

CONTROL SYSTEM:				
☐ Alarm Objective Analysis	☐ Loop Diagrams			
☐ Analyzer Instruments	☐ P&ID Change due to New / Modified equipment			
☐ Chevmon ☐ Control Objectives Analysis	☐ P&ID's Change - Field condition not matching existing P&ID			
☐ Control Room Design	☐ Pressure Measurements			
☐ Control Systems	✓ Process Alarms			
☐ Control Valves	✓ Process Control			
□ DCS	☐ Relief Systems			
☐ Egatrol	☐ Shutdown Systems			
☐ Electrical One-lines	☐ System Design			
☐ Field Installation	☐ Temperatue Measurements			
☐ Flow Measurements				
☐ Honeywell				
☐ Honeywell Process Simulator				
$\hfill\Box$ Instrument Seals, Purges and Winterizing				
☐ Intrinsic Safety				
☐ Ladder Logic Diagrams				
Level Measurements				

SUMMARY OF REVIEW*

No issues. Can change maximum setpoint on bed outlet override controls to 750 DegF (from 800). Override active alarm already exists. Will add 760 DegF alarm to bed temperature indicators.

*When possible include copies of documents referenced in the summary.

ENVIRONMENTAL REGULATORY REVIEW CHECKLIST

You have been assigned a Regulatory Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

MOC Number:	22794
Filing Reference:	
Person Responsible:	Tarter, Donald J.
Completed By:	Tarter, Donald J.
Date Completed:	11/8/2010

Project/Equipment Title:

1310 Max Bed Temperature override @ 750F and low priority alarm @ 760F - Update EOM with Bed Temperature Limit	

1	
Check	that all Apply:
	Chevron:
	Yellow Book
	Correction or Alternations to Refinery Utility System (RI-503)
	CITY OF RICHMOND
	CEQA (EIR's, etc
	City of Richmond Conditional Use Permits (Land use and Hazardous Materials)
	Regulatory
	BAAQMD Air Regulations Permits (including Title V)
	BAAQMD Air Regulations: Additions, modifications, or deletions of VOC Components/Equipment (reg. 8-18 LDAR Program - equipment leaks/fugitive emissons)
	BAAQMD Air Regulations: Wastewater System components - reg 8-8 and NSPS QQQ (process drains, catch basins, manholes, sumps, cleanouts, oil-water separators)
	BAAQMD Air Regulations: Storage Tanks
	BAAQMD Air Regulations: Internal Combustion Engines
	BAAQMD Air Regulations: Flares
	BAAQMD Air Regulations: Boiler, Steam Generators, Process Heaters & Gas Turbines
	BAAQMD Air Regulations: SRU, Tail gas, or H2S Unit Changes
	BAAQMD Air Regulations: Long Wharf (Marine Terminal)
П	Department of Transportation (DOT)

SUMMARY OF REVIEW*

No environmental regulatory issues.

*When possible include copies of documents referenced in the summary.

ENVIRONMENTAL REGULATORY REVIEW CHECKLIST

You have been assigned a Regulatory Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

Project/Equipment Title:

R-1310	Max Bed Temperature override @ 750F and low priority alarm @ 760F - Update EOM with Bed Temperature Limit
	EPA Benzene NESHAP (National Emissions Standards for Hazardous Air Pollutnats) (process vents, storage tanks, watewater systems, transfer operations, fugitive emissions
	EPA Benzene Waste Operations NESHAP (BWON)
	EPA MACT (Maximum Achievable Control Technology) Standards and Subparts (process inits, storage tanks, wastewater system, fugitive emissions)
	EPA NSPS (New Source Performance Standards) and Subparts (storage tanks, flares, wastewater components, fugitive emissions, boilers, process heaters)
	Chemical Inventory / Hazardous Materials Business Plan (e.g. New Chemicals:RI-313)
	Risk Management and Prevention Plan (RMPP)
	RWQCB Waste Discharge Orders, EPA Consent Agreement Sites
	RWQCB NPDES Regulations/Permits
	RWQCB SB-1050, Waste Discharge Requirements (WDR)
	Spill Prevention Control and Counter Measures Plan (SPCC Plan)
	Waste Regulations and Permit
	Wharf and Shoreline Permitting related agencies (BCDC, Army Corps, SLC, USCG, OSPR, EPA)
	Permit to Build and Remove Wells, County Permit Required
	Activities impacting groundwater protection system (GPS) or WDO sites
Yes 1	No
	Any additions, modifications, or deletions of VOC Components/Equipment (including drains or wastewater components) that will change VOC identification/ta

BUILDING PERMITS REVIEW CHECKLIST

Yo is ev

Project/Equipment	Title:
-------------------	--------

ou have been assigned a Regulatory Review. This checklist	Filing Reference		
a guide to help ensure that all information necessary to raluate the change is considered.	Person Responsible	Linares, Elena E.	
aldate the change is considered.	Completed By	Linares, Elena E.	
roject/Equipment Title:	Date Completed	11/8/2010	
-1310 Max Bed Temperature override @ 750F and low priority alarm @ 760F - Update EOM wit	h Bed Temperature Limit		

SUMMARY OF REVIEW*

MOC signed off. A City of Richmond building permit is not required based on the information provided in the scope of work, but is required for any new construction such as: electrical, instrumentation, pipe supports, structural modifications, and etc.

MOC Number 22794

INSPECTION REVIEW CHECKLIST

You have been assigned a Inspection Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

MOC Number: 22794

Completed On: 11/8/2010

Completed By: Bosworth, Gregory A.

Person Responsible: Bosworth, Gregory A.

Project/Equipment Description:

This MOC has been created to change the R-1310 bed temperaturand the metallurgical alarm at 825F will not be changed and will be	e override high setpoint limit to 750F and add a low priority alarm at 760F. The alarm at 760F will be a high alarm be a high-high alarm.
All bed temperatures in R-1310 should remain below 750F to pre-	vent excessive cracking in R-1310. Excessive cracking increases the molecular weight of the recycle gas. High
Yes No Plant Protection/Security Review	The scope of work has been reviewed by the Chevron Fire Marshal. Scope of work

City Fire-Plan Review is Mandato City Fire-Permit is Mandato City Acceptance Test is Mandato Office of Fire Prevention Review On does not constitute a change in fire protection.

HEALTH & SAFETY EVALUATION

Date Issued:	11/5/2010)	Maximo Number:	**	MOC Number	22794
ABU:	RLOP		EWO Number		Filing Reference	
Plant:	LNHF 13 F	lant			Person Responsible	Watson, Stephanie J.
Section 2	Reviewer:	Seidlitz, Micha	ael R.		Completed By	Watson, Stephanie J.
Project/Equipm	nent Title:	R-1310 Max E	Bed Temperature override @ 750F and lo	w priority alarm @ 70	OF - Updat Date Completed	12/8/2010
De	escription:	This MOC has at 760F will b	been created to change the R-1310 bed e a high alarm and the metallurgical alar	temperature override m at 825F will not be	e high setpoint limit to 750F and add a low changed and will be a high-high alarm.	priority alarm at 760F. The alarm
Step 1:	Notify US	w □ι	JSW Representation Present	JSW Representative	:	
Worker's Com	mittee Mer	nber/Steward'	s comments if unable to attend:			
		ations, Mainte			ve: Alan Henrickson Ievant to the change (CRTC, Contractors	, etc)
Step 3: Thi training requir			d. Discuss the existing situation. Disc	uss the change. Dis	scuss the impact of the change on the ex	isting situation. Determine the
manimu redun	ements for	this change.				
Step 4:	ements for	this change.			Training Type: 1	
Step 4:			our options, consider your following:		Training Type: 1	
Step 4: Develop a list	of concern	s, consider yo		ot Work *Confined Spa	Training Type: 1 ce Entry *Evacuation Plan *Safety Operator	Proceed
Step 4: Develop a list *H2S *NH3 *A	of concern	s, consider yo		ot Work *Confined Spa		Proceed Safely
Step 4: Develop a list *H2S *NH3 *A	of concern cid *Caustic	s, consider yo *Benzene *Fa	all Protection *Staging *Scott Air *PPE *He	artificially limited rincrease feed rate	ce Entry *Evacuation Plan *Safety Operator	Safely as added to Yes tially be bed I be ccess the future. appleted in ety aspecs of
Step 4: Develop a list *H2S *NH3 *Ar C Should the lir	of concern cid *Caustic concern mit be set h	s, consider you *Benzene *Fa igher, such	Consequence If the limit is too low, the LNF could be on feed rate. The LNF could potentially	artificially limited increase feed rate remain stable.	Mitigation Mitigation This limit was set with a buffer. A note was the PED section that this limit could potent increased in the future if the LNF is at the temperature limit. However, there should heightened awareness around several provariables if this alarm limit is changed in the Also, the MOC process will have to be conthe future if the limit is raised, so the safe	s added to Yes tially be bed l be cess the future. Inpleted in ety aspecs of insideration.

HSE Action Items

HEALTH & SAFETY EVALUATION

Date Issued: 11/5/2010		O Maximo Number:		MOC Number	22794	
ABU:	RLOP		EWO Number	Filing Reference		
Plant:	LNHF 13 F	lant		Person Responsible	Watson, Stephanie J.	
Section 2	Reviewer:	Seidlitz, Michael R.		Completed By	Watson, Stephanie J.	
Project/Equipm	ent Title:	R-1310 Max Bed Temperature override @ 750F and low priority alarm @ 760F - Updat		Date Completed	12/8/2010	
Description: Th		This MOC has been crea at 760F will be a high a	ated to change the R-1310 bed temperature override high setpoint lin larm and the metallurgical alarm at 825F will not be changed and wil	mit to 750F and add a low be a high-high alarm.	priority alarm at 760F. The alarm	
Additional Cor	nments					

PROCEDURE REVIEW CHECKLIST

You have been assigned a Procedure Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

MOC Number	22794
Filing Reference	
Person Responsible	Henrickson, Alan C.
Completed By	Henrickson, Alan C.
Date Completed	1/11/2011

Project/Equipment Description:

This MOC has been created to change the R-1310 bed temperature override high setpoin the metallurgical alarm at 825F will not be changed and will be a high-high alarm.	nt limit to 750F and add a low priority alarm at 760F. The alarm at 760F will be a high alarm and
All bed temperatures in R-1310 should remain below 750F to prevent excessive cracking	in R-1310. Excessive cracking increases the molecular weight of the recycle gas. High
☐ Alarm Procedures	SUMMARY OF REVIEW*
☐ Any Special or unique hazards	Updated information has been added to LNFPE05, LNFCOD of Vol.1, process description and COD table.
✓ COD/Ops Monitor	
☐ Consequences of deviation	
Control measure to be taken if physical contact or airborne exposure occurs.	
Precautions necessay to prevent exposure, including administrative controls, engineering controls, and personnel protective equipment.	
properties of, and hazards presented by, the chemicals and operation of the process.	
☐ References to additional procedures, such as Safe Work Practices	
☐ Routine Duties	
☐ Safety system and their functions	
☐ Steps required to correct and/or avoid deviation	
Steps fo each operatong Phase	
☐ Emergency	
✓ Normal	
☐ Start-Up/Shutdown	
☐ Temporary	

*When possible include copies of documents referenced in the summary.

Stage Two Training and Communication Review 1/29/2013 10:08:15 AM

	MOC No:	22794
✓ Identify the affected employees. * Maintenance and Technical affected? * Employee who will require training to start up	Date Completed: Completed By:	1/11/2011 Henrickson, Alan C.
the change based on the level of training. * Employees who will receive training after the start up	Person Responsible: Project/Equipm	Henrickson, Alan C. ent Title:
 ✓ Procedures have been modified/written (Ops/SSO/Trainer) ☐ Identify the affected employees * Lesson plan cover sheet (includes training 		Temperature override @ 750F and low priority pdate EOM with Bed Temperature Limit
objective statement and list of affected employees)	Summary of Re	eview:
* Procedural changes (Standing Orders, mark-ups) * Flow daigrams (final or mark-ups)		on has been added to LNFPE05, LNFCOD of cription and COD table.
Determine level of training		
Training has been scheduled		
Affected employees have been trained in order to start up the change.		

APPENDIX III PRE-START-UP SAFETY REVIEW CHECKLIST

You have been assigned a Pre Start-Up Safety Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

Passport No:		MOC Number	22794
EWO No.:		Filing Reference	
MOC PSSR.:	22794.001	Person Responsible	Watson, Stephanie J.
MOOT COIL.		Completed By	Watson, Stephanie J.
		Date Completed	2/22/2011

Watson, Stephanie J.

Project/Equipment Description:

R-1310 Max Bed Temperature override @ 750F and low priority alarm @ 760F - Update EOM with Bed Temperature Limit

Subsystem:

Tuesday, January 29, 2013

NOT The PSSR facilitator shall involve employees with expertise in process operations, maintenance, and engineering, based upon their experience and understanding of the process system being evaluated.

the process system being evaluated.		
The following requirements for PSSR shall be addressed:	Approved by:	Date
 Has the equipment and construction been completed in accordance with the critical design specifications? Some examples of how this may be accomplished are: * Review of equipment quality assurance and inspection records. * Review of construction inspection records. * P & ID "check" after mechanical completion, and facility "walk-through" inspection. 	Watson, Stephanie J.	2/22/2011
Justification: Bed Overrides have been added to DCS		
 2. Are Safety, operating, manintenance, and emergency procedures in place and adequate? * The phrase "in place and adequate" means: written, reviewed, approved, and accessible to employees requiring the procedures in their work. * This does not prevent the use of "mark-up" procedures to satisfy the requirement, but these must undergo the same review and approval and training interaction as would "the final version" of the same procedure and would require rigorous control. 	Watson, Stephanie J.	2/22/2011
Justification: Yes - EOM has been updated		
 3. Has the communication or training of affected operating, maintenance, or contract workers been completed? * Maintenace employees, contractors, and other employees whose work is affected by the change must be informed of the change and training in the impact on their job tasks before the changed equipment is started up. 	Watson, Stephanie J.	2/22/2011
Justification: yes		
 4. Have the quality assurance goals of mechanical integrity been met? * Ensure that changes are suitable for the intended service. * Ensure that the quality of the work is acceptable. * Ensure that the quality of the Leak Seal is acceptable. Justification: N/A	Watson, Stephanie J.	2/22/2011
Justification: N/A		

*When possible include copies of documents referenced in the summary.

5. Have all recommendations resulting from PHA's or HSE's been addressed of resolved

* Ensure tall Recommendations have been documented as addressed or resolved

Page 1 of 2

2/22/2011

APPENDIX III MOC Number 22794 Passport No: PRE-START-UP SAFETY REVIEW CHECKLIST Filing Reference EWO No .: Person Responsible Watson, Stephanie J. You have been assigned a Pre Start-Up Safety Review. This MOC PSSR.: 22794.001 checklist is a guide to help ensure that all information Completed By Watson, Stephanie J. necessary to evaluate the change is considered. Date Completed 2/22/2011 Project/Equipment Description: R-1310 Max Bed Temperature override @ 750F and low priority alarm @ 760F - Update EOM with Bed Temperature Limit Subsystem: Justification: Yes Are there any safety-related exceptions encountered during the PSSR that require follow-up after started up? Miscellaneous Comments: Completed Completed Owner ByOn Notified

Exception

PROP. 1					H 470 MM
	DEV		CHE	C 12 1	
	NEV	LLVV	CHE	UNL	

MOC Number	22794
Filing Reference	
Person Responsible	McCall, Patrick D.
Completed By	McCall, Patrick D.
Date Completed	2/22/2011

Project/Equipment Title:

R-1310 Max Bed T	emperature override @ 750F	and low priority alarm @ 760F	F - Update EOM with Bed T	emperature Limit	

PSI Documents

SUMMARY OF REVIEW*

Procedures updated and posted to the EOM. COD table updated.